

Sediment Transport/Debris Flow Analysis



- **In this case, a massive debris and sediment load was transported, during a very severe storm, from the natural watercourse and deposited at a five-tower condominium complex located in Hawaii. Considerable damage resulted.**

Source of Sediment/Debris



- **The ultimate source of the sediment and debris was the natural steep terrain located upstream of the complex.**

Debris Wall Behind Resort



- **Remnants of the sediment/debris flow are still evident after the clean up. A debris barrier has been placed in the parking lot of the complex.**

Property Damage

