



- **A derailed passenger train car is seen positioned above a wooden railroad bridge that has been subjected to severe erosion.**
- **A concrete erosion control block is seen lying in the foreground.**
- **The erosion at the bridge is easily apparent, and extends several feet into the stream bank.**

Closer Look at the Erosion Damage



- Note the erosion at the bridge.



- The erosion control block is seen lying on its side in the foreground.