

Flood Water Over An Emergency Spillway



- **The massive failure of a set of dams in Canada led to significant damage and losses. Dr. Hromadka and his team provided inspection and documentation services, such as these photographs, as well as the investigation of causation factors.**

Erosion of River Banks



Damage on Bridge Abutment



Damage Along Floodway

